

DOC'S BLOCKS
AUTOMOTIVE AIR CONDITIONING REPAIR

VACUUM CHART

Remember to change the oil in your vacuum pump. Old oil will reduce pump efficiency. Replace with recommended oil frequently.

Vacuum needed to boil water at shop temperature

System vacumm	Boiling point
24.04	140.00
25.39	130.00
26.45	120.00
27.32	110.00
27.99	100.00
28.50	90.00
28.89	80.00
29.18	70.00
29.40	60.00
29.66	50.00
29.71	40.00
29.76	30.00
29.82	20.00

Subtract 1 inch for every 1000 ft. above sea level.